



# How is the salinity s24/785ke Kate



## Contents

Executive Summary.....	2
1.0 Introduction.....	3
2.0 Theoretical Framework and Literature Review.....	3.....
3.0 Methods.....	4
3.1 Equipment.....	4.....
3.2 Data Collection.....	5.....
3.3 Data Processing.....	5.....
4.0 Results.....	6
5.0 Discussion.....	14
5.1 Tidal Influences.....	14.....
5.2 Weather Influence.....	14.....
5.3 Effect on nanga Spawning.....	14.....
5.4 Further Research.....	15.....
5.5 Anomalies.....	15.....
6.0 Limitations.....	16
7.0 Conclusion.....	17
8.0 Acknowledgments.....	17.....
9.0 References.....	18
Appendices.....	19

## Executive Summary

- x The aim of this research was to answer the following questions; how is the salinity of Lake Kate Sheppard (LKS) affected by its inflows and outflows? Are these salinity conditions favourable for Inanga spawning?
- x Avon t karo Network (AvON) is interested in LKS as a possible mahinga kai site due to its suitability for Inanga spawning. Salinity is a dominant factor that

## 1.0 Introduction

LKs an anthropogenidakecreatedfor flood mitigation

Zhang & Carrick (2014) examined LKSs



## 4.0 Results




Figure3: Graphshowingthe averagewind speedvaluesduring data collection

Figure4: rainfall data for August2015.Dueto the weatherstation being



Figure




Figure7: Lowtide two days of rainfall.



Figure8: Lowtide no rainfall for the previous week.






Figure10: Hightide no rainfall for four days.

Results have been obtained from the processed pot testing data.






Figure 11: Graph showing the onset of spawning relative to high tide. Retrieved from Richard & Taylor, (2002.)




Figure 12: Graph showing the relationship between the spawning locations and proximity to the salt water wedge. Retrieved from Richard & Taylor, (2002).

#### 5.4 Further Research

- x More salinity profiles of the water should be collected throughout LKS at high and low tides, especially during autumn, when nanga spawn to observe seasonal trends.
- x Continuous data is needed to gain a clearer understanding of how the salinity profiles evolve with the change



## 6.0 Limitations

- x It was difficult to determine when the logger had reached the bottom of the lake at locations due to poor visibility and drag from water flow.
- x Malfunctions with the RBRCTD and CT2X recorders limited the expansion of the final data sets, preventing the collection of any continuous data throughout the time of this research. Two CTD recorders were found to be faulty when organising available equipment at the start of the project. These recorders were sent away for inspection and repairs, however these recorders were not fixed in time for implementation in the field. A catastrophic failure of a CT2X recorder meant four weeks of continuous data was lost. Water had infiltrated the recorder, consequently damaging and corrupting the hardware inside (figure 13). With recording devices limited already, the loss of this valuable data was a cruel setback. As a group it was decided that data from previous years could be used replacing this lost data.

Figure 13: Picture shows the top cap of the CT2X that failed, allowing water into the unit. The spring for the battery circuit is rusted, indicating that the equipment had failed a week or more before we realised.

- x No previous experience with equipment meant valuable time had to be used to understand the basics before going into the field. Although this meant we lost a week of data collection, this was needed to ensure the data was collected correctly.
- x Time was the biggest limitation while conducting this research project. Attempting to have all data collection, data processing and reporting done within twelve weeks was challenging. If there was a longer deadline, the expansion and quality of data could have been a lot better. This would therefore allow for more accurate conclusions to be made.
- x Weather conditions when taking spot measurements in the field was a factor in depth recordings. Some days the recorders have measured a minimum depth of 0.2m, which is incorrect. This could be an atmospheric effect or due to the sensors not being calibrated correctly.
- x Accurate climate data of the LKS area has not been available and



this

to



## 9.0 References

Avon Otakaro Network. (2013). Our Charter. Retrieved October 7, 2015, from Avon Otakaro Network:  
<http://www.avonotakaronetwork.co.nz/aboutus/charter.html>

Barr, E.,





Figure A.4: An Odyssey CTD logger was used to measure continuous data however due to misinterpreted day times the equipment was not installed at true low tide thus the equipment was not placed deep enough and data wasn't collected at low tide.




Figure A.5: Installation of the first CT2 logger beside the jetty in LKSA waratah was driven into the lake floor with the logger secured to it. This provided reassurance that the logger won't move around, and makes it difficult for members of the public to interfere.



Figure A.6: Individual waypoints can be seen on the screen of the GPS location order was recorded in a notebook.




Figure A.7: The CT2 logger that was stationed at the dock. This is the same unit that was damaged.