Waikato Regional Council Technical Report 2018/11

# Making good decisions: Risk characterisation and management of CCA post hotspots at vineyards and kiwifruit orchards

www.waikatoregion.govt.nz
ISSN 2230-4355 (Print)
ISSN 2230-4363 (Online)

Waikato Regional Council

Peer reviewed by:
Simon Beardmore
Davina McNickel

Date June 2018

Approved for release by:
Dominique Noiton

Date July 2018

**Disclaimer**

This technical report has been prepared for the use of Waikato Regional Council as a reference document and as such does not constitute Council's policy.

Council requests that if excerpts or inferences are drawn from this document for further use by individuals or organisations, due care should be taken to ensure that the appropriate context has been preserved, and is accurately reflected and referenced in any subsequent spoken or written communication.

# 1 Introduction

Copper, chromium

# 3 A regulator's role

Literature shows that the leaching of arsenic can result in soil around posts exceeding recommended standards by multiple orders of magnitude. Under the New Zealand regulatory framework, contaminants in soil that may affect human health are managed under the National Environmental Standard for Assessing and Managing Contaminants in Soil to Protect Human Health (hereafter referred to as NESCS) during a change in land use, development or subdivision. However, there is no reliable guidance to guide a consistent pattern of regulatory action for assessing and addressing the risks to human health posed by CCA treated timber posts; particularly in areas of heavy use such as vineyards and kiwifruit orchards.

Currently, regulators take a variety of approaches to the issue of fence post hotspots in soil; largely led by the recommendations of the consultants acting on behalf of their clients. In most cases, the issue is neglected or ignored in conceptual site models; only to raise it6.6r0.4 (o)-6.6 (n)29pf a3

# 4 Literature review

## 4.1 Fence post impact on soil and groundwater quality

The use of treated timber is not generally noted in New Zealand as a significant source of arsenic contamination in soil (e.g. McLaren, 2006); however, many recent publications are beginning to note potential health and environmental effects from the useof treated timber. Of particular note in New Zealand, horticultural operations such as vn.2 (e)-3 Lt ute p;r. 1.9 (h)2.3tts shen(s)9.7.1 (at)-3 11

did find evidence of adverse health effects from exposure to burning CCA treated wood and from improper handling of wet treated timber; they only discovered one case of possible adverse effects from arsenic contaminated soil. They could not conclude whether a lack of impact from arsenic contaminated soil was due to an actual lack of toxic effect or a failure to detect and measure those effects. They conclude that the common assumption of risk managers that CCA leaching from timber structures does not pose a risk is based on the lack of adverse effects data, when in reality there is plenty of scientific literature indicating that soils under or adjacent to CCA structures may pose a risk.

of NZ affected by volcanic and mineralised geology (e.g. Waikato, Coromandel, Central Otago).

- Children 2-6 years old are considered the most at risk due to hand to mouth behaviour.
-

**Table 2: Summary of case studies**

| Case Study | Horticulture type | Location | Climate[4] Mean annual rainfall (mm) | Geology | Soil Type | Age/dates of operation | Framework type/density | Future land use scenario |
|---|---|---|---|---|---|---|---|---|

| Case Study | Horticulture type | Location | Climate[4] | Geology | |
|---|---|---|---|---|---|

| Case Study | Horticulture type | Location | Climate[4] | Geology | Soil Type | Age and dates of operation | Framework type/density | Future land use scenario |
|---|---|---|---|---|---|---|---|---|

# 6 Risk characterisation

## 6.1 General

Risk characterisation is the assessment of the potential for adverse health effects to occur, in this case from arsenic concentrations in soil originating from the use of CCA posts in vineyards and kiwifruit orchards. Risk characterisation conveys the risk assessor's judgement as to the nature and existence (or lack of) human health risks, in an informative and useful manner for decision makers.

The risk to a future receptor (e.g. a child or adult) will depend on the type and amount of exposure the receptor has to impacted soil. It is clear from the available information in the literature and the available case studies (Section 4) that arsenic impacts in soil associated with CCA posts are localised to an area around each post. Therefore, if impacts were to remain at the site following development for residential use (without any form of remediation or risk mitigation), the following exposures are possible:

- Scenario 1: The receptor could come into contact with soil from acroith sst.8 (n(r73 Tw 1.1 (e)7.

support this assumption. It is noted that if the extent of impact is larger around the larger posts, the calculations below may underestimate potential risk issues.

- The extent of the impacted soil around the posts was up to approximately 200 mm laterally from the post and approximately 500 mm deep.

Background concentrations of arsenic (away from posts) were typically close to or less than 10 mg/kg.

The potential volume of impacted soil around each post, and potential volume of impacted soil within a future residential lot (ba.6 (.)-1 ( )]T6 (m)td2.3 (d)13.1 ( p) re3 -1.391.2 ( a)10.6 ( fu)2.3 (t)-3 (u)2.3 (re

**Table 4: Summary of potential extent of arsenic impacts in soil around stacks/piles of posts**

| Parameter | Value |
|---|---|
| Area of soil potentially used for piles (assuming 600 $m^2$ size block and 50 $m^2$ per ha*) | 3 $m^2$ |
| Lateral extent of impacted soil around pile | 0.5 m |
| Area of arsenic impact on residential lot (assuming square pile area) | 7.5 $m^2$ |
| **% impacted soil on area basis over 600 m2 site (surface soil)** | **1.2%** |
| Depth of impacted soil beneath piles | 0.15 m |
| Volume of impacted soil on residential lot | 1.1 $m^3$ |
| Total volume of soil per 600 $m^2$ lot (to 150 mm depth) | 90 $m^3$ |
| Total volume of soil per 600 $m^2$ lot (to 500 mm depth) | 300 $m^3$ |
| **% impacted soil in top 150 mm of a residential lot** | **1.2%** |
| **% impacted soil in top 500 mm of residential lot** | **0.4%** |

* refer to footnote 5, where the placement of stacks/piles on a vineyard may result in soil impacts that may be distributed across the vineyard, with the stack/piles commonly placed at the head row. It is noted that should a subdivision result in land that is dominated by the former head rows only, the calculations in the above table may underestimate potential risk issues. If the subdivision does not include any land that was used for stacks/piles of posts then the above may underestimate potential risk issues. As the specific relevant to any one site are not know, the above is adopted as an indicative average.

# 6.3 Potential risks to health

[redacted]t standards for residential land use have been derived on the basis of ions, relevant to the assessment of potential long-term or chronic luated on the basis of a non-threshold dose-response relationship, n the basis of exposures to occur as a child (aged 1-6 years) and an standard residential and 7-30 years for rural residential) combined. the use of a non-threshold risk-dose of 0.0086 µg/kg/day, which is $10^{-5}$) risk level[6].

osures by young children and adults the following default exposure assumptions are adopted (Ministry for the Environment, 2011a):

**Table 5: Summary of exposure assumptions in SCS: standard/rural residential**

| Exposure assumption | Value adopted for standard residential (values that differ for rural residential in brackets) | |
|---|---|---|
| | Child | Adult |
| Body weight (kg) | 13 | 70 |
| Averaging time (non-threshold) | 75 | 75 |
| Exposure frequency (days/year) | 350 | 350 |
| Exposure duration (years) | 6 | 14 (24) |
| Soil ingestion rate (mg/day) | 50 | 25 |
| Inhalation rate ($m^3$/day) | 6.8 | 13.3 |
| Skin surface area that is dirty ($cm^2$) | 1900 | |

- x 55.3 mg/kg which is the 95% UCL of arsenic concentrations close to posts reported in Case Study 12[8]. This value is similar to the 95% UCL from Case Study 11 and representative of the lower end of the 95% UCL values reported.

The calculated weighted residential soil

# 7 Soil mixing as a mitigation method

Vertical mixing of soil is one risk management strategy that can be utilised as a risk mitigation strategy for large sites that contain chemicals above the soil guideline value. The generally accepted rule of thumb in the New Zealand contaminated land sector (Ministry for the Environment, 2006) is that soil mixing is inappropriate for hotspot contamination containing contaminants more than 2-3 times the relevant guideline. In addition, New South Wales Environmental Protection Agency (2003) and Pattle Delamore Partners (2015) indicate that vertical mixing is not recommend for "isolated hotspots"; however, given the number of CCA posts normally installed at vineyards and kiwifruit orchards (up to 600/ha), the term "isolated hotspot" is not representative of the distribution of potential impacts present in this instance.

What is considered more important is the number of hotspots and arsenic concentration in the hotspots as this will affect the validity of the use of vertical or lateral mixing to reduce concentrations in soil to below the guideline levels. Further, a hotspot is often defined in guidance documents as a concentration greater than 2-3 times the guideline value. While this may be appropriate for large volumes of impacted soil in individual hotspots, it may not be appropriate for small soil volumes that are numerous, and spread across larger areas. Therefore, in this document, the term "arsenic impacted soil", or "micro-hotspot" has been used in preference to the generic term "hotspot".

If the estimated depth of mixing required to achieve a safe contaminant concentration is greater than 500 mm, New South Wales Environmental Protection Agency (2003) and Pattle Delamore Partners (2015) do not recommend vertical mixing as a risk mitigation strategy as homogenisation of soil to a depth (8 ( large0.039. (e)-3a1 T20) T.5651 (t)-5.88 ( )0.5 ((a)7.6 (sp)-5.9 (r)10.6 (d)

| Post Type | Background | Maximum Arsenic Concentration | Concentration post mixing |
|---|---|---|---|

# 8 Effective soil mixing techniques

This section discusses typical New Zealand land development techniques and equipment as known to the document authors and how they might be implemented to mitigate risk to protect human health. The authors recommend that while soil mixing might be a viable remediation method, effective soil mixing is not easily achieved and certain standards will be required to achieve the desired result (some more rigorous than other depending on soil type and condition).

Not all in-situ soil mixing techniques are equally effective and so the case study examples given here may give regulators and developers a better idea of techniques that may prove effective for their own regions. However, regardless of this there are multiple methods that can achieve effective soil mixing and we make it clear that the methods noted below are examples only rather than an exhaustive list. For untested methods, regulators may wish to consider recommending a more iterative process where mixing can be repeated based on validation results until clean-up goals are attained.

Although there are numerous different methods of land development, they can generally be broken into three types:

1. Developments where topsoil is pre-stripped, allowing the site to be re-levelled using motor scrapers. Topsoil is generally stockpiled, often screened, and then re-spread upon completion of earthworks and stormwater system development. These sites are generally large scale developments, involving a large number of resulting sections and tend to utilise more specialist and large scale equipment.
2. Smaller scale developments where the soil is stripped but retained on the subject site; the landowner redistributes the soil around the individual property as they see fit.

Martinez-Sanchez MJ, Martinez-Lopez SM, Martinez-Martinez LB, Perez-Sirvent C 2013. Importance of the oral arsenic bioaccessibility factor for characterising the risk associated with soil ingestion in a mining-influenced zone. Journal of Environmental Management 116: 10-17.

McLaren R 2006. Extent and severity of arsenic contamination in New Zealand. In: Naidu R, Smith E, Owens G, Bhattacharya P, Nadebaum P eds. 2006. Managing a-

Zagury GW, Sampson R. Deschenes L 2003. Occurrence of metals in soil and groundwater near chromated copper arsenate-treated utility poles. Journal of Environmental Quality 32:507-514.

# Appendix A. Case study details

| Case Study 1. Vineyard 1, Te Kauwhata | |
|---|---|
| Site details/Site history | The site has an approximate area of 17 ha. The adjoining properties are residential, rural residential and pastoral. Two ponds and a wetland area are present at the site.<br><br>The site was formerly a vineyard with the whole site used for growing vines at some stage. Vineyard activity evident in aerial photographs (including 1942, 1963 and 1977). Vines were still present at the time of site investigation in 2016.<br><br>A mix of strainers (full round posts 140 mm-225 mm diameter) and half rounds (generally 140 mm-180 mm). |
| Proposed development | Sub-division into approximately 130 residential lots of approximately 800 $m^2$ each. |
| Geology/Soil type | The 1:250,000 and 1:63,360 scale geological maps show the site to be underlain by pumiceous clays with lignite, gravel, and some pure pumice silt and sand from Pliocene epoch.<br><br>Soils are volcanic in origin, deposited as alluvium with interbedded peat materials and are part of the Whangamarino and Puketoka Formations.<br><br>Intrusive investigations have proved the site to be underlain by interbedded clayey silt/silty clay and sandy soils with varying proportions of silt in them. On the hill sides and ridgeline the topsoil is underlain by low permability clay rich soils. In the valleys the topsoil is underlain by thick silt rich soils which is expected to have a low to intermediate permeability. |
| Depth to ground water | Groundwater was not encountered in any of the trial pits or hand auger holes along the ridgeline.<br><br>Interpretation Tc 0 Tw ( )TjETEM.1 (t)2.6 (e)9.1ateo5 ( a)2.1 (nd r)o.4 (o).1 (a)2.1 (t)2mm[(l)4 (nt)3p0 0 9.961 |

samples (39 mg/kg and 25 mg/kg) were collected 200 mm from a post with one additional sample (25 mg/kg) collected 600mm from a post. The majority of the results for the remaining samples were considerably below the adopted guideline value of 20 mg/kg.

Testing of subsoils below the posts and strainers in the vine growing areas

# Case Study 3. Vineyard 3, Blenheim

| | |
|---|---|
| Site details/Site history | The site has an approximate area of 21.4ha. The adjoining properties are rural residential and pastoral. The site is approximately 400 m from the Taylors River. |

# Case Study 6. Multiple Hawkes Bay Vineyards

| | |
|---|---|
| Site details/Site history | Several vineyards in the Gimblett Gravels winegrowing region.<br>Full round posts, age range from 6-16 years. |
| Proposed development | Not applicable (MSc Thesis). |
| Geology/Soil type | Dominated by the Omahu soils, fine sand to fine loamy sand topsoil overlying stony gravels interlaid with sand. River sediments, free-draining gravels, low organic content and water holding capacity. |
| Depth to ground water | 30 to 40 m bgl |
| Soil sampling | |

# Case Study 7. Kiwifruit Orchard 1, Bethlehem

| | |
|---|---|
| Site details/Site history | The site has an approximate area of 3.2 ha and is currently occupied by the Mills Reef Winery with associated residential properties, sheds, kiwifruit orchards and avocado trees. The adjacent land uses are vacant fields, fruit orchards and residential dwellings. No surface water bodies are located on the site. The Wairoa River is located apprc5i1.1 (ac)-1tSitRiotOe lu50 1 (t89.1 (e3-6.4 (y4)-9.1 (e)-1 (h-3.4 (a)-3.9(t)-8.4 ( a3.9 |

# Case Study 8. Kiwifruit Orchard 2, Tuakau

| | |
|---|---|
| Site details/Site history | The site has an approximate area of 5.3 ha and is used as a kiwifruit orchard with an associated residential dwelling and storage shed. The site is located in a rural area known for production. The Waikato River is located approximately 1.7 km to the west of the site. A small tributary of the Waikato River, which is the receiver for site drainage from the site, is located near the western site boundary.<br><br>The site has historically been used as a kiwifruit orchard on two occasions - during the 1980s and again in the 2000s until 2016.<br><br>Post details are not provided. It is also unclear whether the posts for the 1980s orchard were removed prior to the second stage of kiwifruit growing. However, the report notes that it is likely the posts were removed, and the ground deep ploughed to break up kiwifruit root work prior to pasture establishment. This means that is it likely that the posts used between 2000 to 2016 were newly established posts. |
| Proposed development | Subdivision (no. 1 lot) - 1 residential lot |

# Case Study 9. Kiwifruit Orchard 3, Pyes Pa

| | |
|---|---|
| Site details/Site history | The site is located on an elevated ridge and comprises a kiwifruit orchard. Associated residential dwellings and infrastructure and a fruit orchard are also present. The site area is not stated. There are no surface water bodies onsite. The nearest surface |

# Case Study 10. Kiwifruit Orchard 4, Hamilton

| | |
|---|---|
| Site details/Site history | The site has an approximate area of 4.04 ha and is used as a Hayward variety kiwifruit orchard with currently no proposal to redevelop. The site is located in a rural area outside of Hamilton City known for horticultural purposes. The Mangaonua Stream runs along the southern boundary of the site, approximately 100m south of the sampling locations<br><br>The frames in this orchard are approximately 30 years old. The framework consists of two 12 inch strainer posts at ends of rows (approx. 2 m apart) with a horizontal 6 inch post between them for bracing. 6 inch posts are used at a 6 m spacing within rows, with 4 m between rows. This equates to approximately 450 posts per hectare. |
| Proposed development | None. |
| Geology/Soil type | Late Pleistocene river deposits, Hinuera Formation, Tauranga Group. Orthic Gley soil, poorly drained sandy loam. |
| Depth to ground water | Domestic supply bore on a property across the road is drilled to a depth of 7 m; therefore groundwater is inferred to be less than 7 m deep. |
| Soil sampling | The soil assessment selected three post locations; two being 6 inch posts within rows and one 12 inch strainer at the ends of the rows. After soil samples were removed from the latter post; it was determined that there had been some soil disturbance in this area, probably designed to restabilise the post. Soil sampling comprised the collection and analysis of 12 samples around each post location as per the schematic below. |

There did not appear to be a significant difference between the level of arsenic concentrations between the 6 inch and 12 inch posts (although this may be an artefact of soil disturbance around the 12 inch post). Without exception, all samples collected within 150 mm of the post exceeded the NESCS rural residential guoB.8 (s)10(t)-3.3 (i)(ur937.1 (s)1.l2.1 (r)4.3.3 (i)(u) F7 ( g)-1

# Case Study 11. Kiwifruit Orchard 5, Te Awamutu

| | |
|---|---|
| Site details/Site history | The site has an approximate area of 8.23 ha and is used as a Hayward variety kiwifruit orchard with currently no proposal to redevelop. The site is located in a rural area on the peri-urban fringe of Te Awamutu. The Mangapiko Stream is located approximately 1 km to the east of the sampling area.<br><br>The frames sampled in this orchard are approximately 13 years old; although much of the orchard frames are 30 years old. The framework consists of two 12 inch strainer posts at ends of rows (one sawn off 30 cm above ground level), 1/4 round posts within rows at 6m spacings; with 3.5 m between rows. This equates to approximately 514 posts per hectare. |
| Proposed development | None. |
| Geology/Soil type 5.1 (68 600.7)-3.9th.7oProp 30 | Early- |

# Case Study 12. Vineyard 6, Central Otago

Site details/Site history

The site has an approximate area of 10.9 ha. Pinot Noir is the predominant variety grown. There is currently no proposal to redevelop the site. Lake Dunstan is located approximately 150 m from the closest part of the site.

Annual rainfall is relatively low, with median rainfall between 375 and 400 mm per year.

Two areas of the vineyard were sampled. The first area was planted approximately 16 years ago; the second was planted 2 years ago. 100 mm average face quarter round posts are used throughout the vineyards. The posts are spaced 8

r6eat-6.1 6 (w.4 (t)-e)-9.1 (r -6.3 (el)-3.9t)-wed-4.4 (s)1.5 (t)-6.4 ( i(n)-6.1 0)]TJ er

**Table 8:**

| Country/ Agency | Regulatory decision for residential/ domestic use and basis | Risk assessment approach (refer to footnote below table for acronym definitions) | | | Residential soil guideline |
|---|---|---|---|---|---|
| | | Exposure | Hazard/ Toxicity | Risk estimates | |

So, for a maximum concentration of 220 mg/kg arsenic in soil at a hotspot, the chronic intake is calculated as follows:

$$\text{Chronic Intake}_{soil} = 220\frac{mg}{kg} \text{ x } \frac{50\frac{mg}{day} \text{x } 100\% \text{ x } 0.000001\frac{kg}{mg} \text{x } 350\frac{days}{year} \text{x } 6 \text{years}}{13 \text{ kg x } 6 \text{ years x } 365\frac{days}{year}} (mg/kg/day)$$

$$= 0.00081 \text{ mg/kg/day} \qquad \textbf{...Equation 5}$$

The quantification of potential exposure and risks to human health associated with the presence of

Where pica involves ingesting 1 g/day: